



E38 mA OVERLOAD ERROR TROUBLESHOOTING GUIDE



TROUBLESHOOTING PROCEDURE

Hey there Subscriber,

Press the button above to view our troubleshooting procedure for an E38 mA OVERLOAD error code.

The procedure above includes common things to check for in order to help with troubleshooting this error without having to reach out to our Technical Support team.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

**Congratulations to the
Field Service Engineers
who have completed
certifications:**

**Russel Absher on SRS
Pocket**

LOCATE US

**SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714**

CONTACT US

tscalls@summitindustries.net

customerservice@summitindustries.net

[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

