



E21 TUBE **INTERLOCK** ERROR TROUBLESHOOTING GUIDE



TROUBLESHOOTING PROCEDURE

Hey there Subscriber,

Click the button above to view our troubleshooting procedure for an E21 TUBE INTERLOCK error code.

The procedure above includes common things to check for in order to help with troubleshooting this error without having to reach out to our Technical Support team.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM →

[LOCATE US](#)

[CONTACT US](#)



SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)