


Troubleshooting Guide

E71 mA FEEDBACK DISABLE ERROR

Note: This is a reminder error for the installer.

INVALID SETTINGS & SELECTIONS			
Error	AP Display	Likely Cause	How to clear the fault
E71	mA FEEDBACK DISABLED	mA feedback turned off	Turn on mA feedback (Set DIP1-4 to ON/CLOSED/RIGHT)

Upon completing AUTOCAL, you must set DIP1-4 on the SYSTEM CONTROLLER BOARD to the ON position to enable mA feedback feature.



System Controller Board