



⚙️ E28 PREP ERROR ⚙️ TROUBLESHOOTING GUIDE



TROUBLESHOOTING PROCEDURE

Hey there Subscriber,

Select the procedure above to view our troubleshooting guide for an E28 PREP error code.

The procedure above outlines a few possible causes for the error code that you can check for in order to help with the troubleshooting process without having to reach out to our Technical Support team.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM →

Congratulations to the
Field Service Engineers
who have completed
certifications:

Brent Herauf on Agility & Agility+

Eric Ramsey on DFMTs

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net

customerservice@summitindustries.net

[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

