



Calibrating AEC for Precision



AEC CALIBRATION PROCEDURE

Hey there Subscriber,

Press the button above to view our updated AEC calibration procedure for Claymont Solid State Ion Chamber and SHFR 400 Generator.

Whether you're performing the initial setup or working on an existing system, this resource provides clear instructions to make calibration easier and reduce the need for additional assistance from Technical Support.

Need to order the phantoms? Just call our operations team and mention part IDs [09907-001](#) or [09907-002](#).

Simply follow the procedure using the button above or go to summitxray.com to learn more.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM →

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

