




SHFR COMPATIBILITY **WARNING**



Hey there Subscriber,

When using the SHFR **Tech Service Console**, you may encounter a pop-up error during initial communication with the generator. THIS WARNING SHOULD NOT BE IGNORED—running an incompatible service utility version can result in improper configuration or operation.

Because version compatibility is critical (especially on SHFR systems with UARC), the best solution is to try a different version—newer or older—until the pop-up no longer appears.

A full library of SHFR service utility versions, along with tube catalogs, is available on our documentation portal:

SHFR Documentation and Utilities



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
(773)588-2444 or (773)353-4000



