




AEC Calibration for Claymont SS AEC Sensor and SHFR 400 Generator



AEC CALIBRATION PROCEDURE

Hey there Subscriber,

Press the button above to view our revised AEC calibration procedure for Claymont Solid State Ion Chamber and SHFR 400 Generator.

Whether you don't know where to start or you are stuck at one of the steps during calibration, this tool should be able to help troubleshoot without reaching out to our Technical Support team.

Simply follow the procedure from the button above or go to

summitxray.com to read more about it.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM ---->

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

