




E15 AND E16 ERROR TROUBLESHOOTING GUIDE



TROUBLESHOOTING PROCEDURE

Hey there Subscriber,

Click the button above to view our troubleshooting procedure for an E15 PREP PRESSED & E16 EXPOSURE PRESSED error code.

Whether you are working with an AP Console or a 2PT Console, this tool should be able to help with troubleshooting without you having to reach out to our Technical Support team and wait in the queue.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

