




Generator Regulation SHFR Error Codes



MAIN TAKEAWAY

These errors relate to generator output regulation and exposure control feedback

Hey there Subscriber,

These following errors involve.....

- **Err 016 – Small Fil Current Range**

Reset, reboot, call service if needed

- **Err 019 – mA Without Exposure**

Reset, reboot, call service if needed

- **Err 020 – kVp Without Exposure**

Reset, reboot, call service if needed

- **Err 025 – Large Fil Demand**

Reset, retry technique, call service if needed

- **Err 026 – Small Fil Demand**

Reset, retry technique, call service if needed

- **Err 040 – Imbalanced kVp**

Reset, reboot, call service if needed

- **Err 041 – Imbalanced mA**

Reset, reboot, call service if needed

 **Need full troubleshooting steps?**

See the **SHFR Error Code Operator Guide** for detailed procedures:

Err 016 (pp. 75- 77) • Err 019 (p. 79) • Err 020 (p. 80) • Err 25 (p. 83) • Err 26 (p. 84) • Err 40 (pp. 92- 94) • Err 40 (p. 95- 97)

Open SHFR Error Code Guide



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

LOCATE US

**SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714**

CONTACT US

**tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)**

