



SHFR Communication

Error Codes



Hey there Subscriber,

These following errors involve.....

- Err 030 — Corrupt RTC
Reset, reboot, call service if needed
- Err 031 — Timestamp Check
Reset, reboot, call service if needed
- Err 042 — Corrupt Counters
Reset, reboot, call service if needed
- Err 043 — Corrupt Error Log
Reset, reboot, call service if needed
- Err 045 — Corrupt Tube Data
Reset, reboot, call service if needed
- Error 74–78 — Generator Reset Errors
Reset, reboot, call service if needed

 **Need full troubleshooting steps?**

See the **SHFR Error Code Operator Guide** for detailed procedures:

**Err 030 (p. 87) • Err 031 (p. 88) • Err 042 (pp. 98) • Err 043 (p. 98) •
Err 045 (p. 99) • Err 74- 78 (pp. 113- 114)**

SHFR Error Code Guide



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

LOCATE US

SUMMIT INDUSTRIES
7555 N CALDWELL AVE
NILES, ILLINOIS 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

