




WHY MAINTENANCE MATTERS



Keeping
Systems
Strong— One
Service at a
Time



Hey there Subscriber,

If you are experiencing HV fault errors or noticing arcing on the tube, it may be an indication that routine maintenance is overdue.

X-ray tubes require regular inspection and upkeep to ensure proper function. Without consistent maintenance, components can degrade over time, leading to performance issues such as high-voltage faults, image artifacts, or even premature tube failure.

Performing scheduled maintenance not only extends the life of the tube but also helps maintain system safety and reliability.



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM>

Congratulations to the Field
Service Engineers who have
completed certifications:

Insert name here

LOCATE US

Summit Industries
7555 N Caldwell Ave
Niles, Illinois 60714

CONTACT US

tscalls@summitindustries.net
customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)

