





DFMT Retrofit Kit



**IN WITH
THE NEW**



**OUT WITH
THE OLD**



Summit Industries is introducing a **Retrofit Kit (P/N 10097)** designed to strengthen horizontal SID calibration issues on J700 DFMT systems. This upgrade provides a long-term fix, improving stability and reducing the need for recalibration.

This product improvement will also be standard on all new DFMT systems coming out of production before year-end.

Give a call to our Summit Operations team to put in an order for your existing systems! Any questions or inquiries should be directed to tscalls@summitindustries.net.

Summit Part Number: 10097

Description: KIT, RETROFIT, GEAR POT HSID, J700 DFMT



Have More Questions?

Browse our authorized dealer portal website. This site contains documentation to assist with installation, maintenance, and troubleshooting of Summit supported X-ray equipment.

SUMMITXRAY.COM →

LOCATE US

SUMMIT INDUSTRIES

CONTACT US

tscalls@summitindustries.net



7555 N CALDWELL AVE
NILES, ILLINOIS 60714

customerservice@summitindustries.net
[\(773\)588-2444](tel:(773)588-2444) or [\(773\)353-4000](tel:(773)353-4000)